



WWW.Q-CARD.COM

ISO Certified* RM-7811 Calibration Cards

For Magnetic Stripe Applications (secondary reference cards)

RM-7811-2 Calibration Card Loco

- Low coercivity calibration card
- Q-Card/PTB* Calibrated
- ISO ID1 size

RM-7811-6 Calibration Card Hico

- High Coercivity calibration card
- Q-Card/PTB* Calibrated
- ISO ID1 size

When to Use Test Cards

Test cards are valuable for:

- Calibrate signal amplitude of magnetic stripe test equipment
- Calibrate the encode current of magnetic stripe test equipment



* Q-Card has assumed responsibility for providing secondary reference cards in compliance with both ISO/IEC 7811-2 low coercivity recording techniques and ISO/IEC 7811-6 high coercivity recording techniques.

Q-Card has transferred the technology used to produce the official magnetic stripe reference cards from Physikalisch-Technische Bundesanstalt (PTB), which has ceased to offer these services.

Reference cards contain a magnetic stripe that produces a known amplitude at saturation. These cards can be used to calibrate magnetic stripe analyzers, which are needed to verify quality during the manufacturing process of cards and tickets that include a magnetic stripe, such as credit cards, hotel key cards and transit tickets.



301 Reagan Street
Sunbury, PA 17801 USA
Phone: 570.286.7447
Fax: 570.286.2649
www.q-card.com



800-717-8007